WILLOUGHBY

WATER POLLUTION CONTROL CENTER

MAXINE L. TICKNOR . Superintendent

WILLOUGHBY MUNICIPAL HALL

WILLOUGHBY, OHIO 44094

PHONE 94 0160

May 21, 1986

Ms. Sandy Kausek Ohio Environmental Protection Agency 2110 E. Aurora Rd. Twinsburg, OH 44087 MARIL

RE: Ohio Rubber Company

Dear Ms. Kausek:

We are in receipt of a copy of the report from Brundage, Baker, and Stauffer, Limited, regarding the mapping and identification of sewers at Ohio Rubber. It is our understanding that you have already received this report. A brief review of the blueprints revealed the fact that all floor drains, with few exceptions, discharge to the storm sewer. This situation has not been allowed to continue in other companies within our service area.

Please also note that the floor drain mentioned on page 6, section 6, paragraph 2, was tributary to the storm sewer.

. Upon completion of your review of the plans and report, please provide us with a copy of your response. If you have any questions regarding this matter, please do not hesitate to call.

Respectfully,

WILLOUGHBY-EASTLAKE
Water Pollution Control Center

Maxime L. Julena

Maxine L. Ticknor Superintendent

US EPA RECORDS CENTER REGION 5

450047

MLT:dps

Enclosures:

cc: George W. Tegner, Willoughby Service Director Susan Vargo Roseum, Industrial Waste Analyst File RECEIVED

MAY 2 2 1988

OHIO EPA-N.E.D.O.